

- After a part has been created in the system (for example bearings) and a resource (for example detergent), then it is possible to create purchase orders in DMM. Each purchase order defines for example quantity of parts or resources that is ordered and from whom.
- (2) Man-hours, as estimated cost for work orders, are estimated per role.... a work order can for example contain an estimate for 10 hours from a mechanic and 10 hours from an electrician. When it is time to carry out work on a work order, then it is possible to distribute estimated hours to individual employees, for example John the mechanic and Smith the electrician. Administrator defines the set of roles

